

Iron

ANNUAL SURVEYS.

33884
12812

No. 277 Survey held at London Date June 19th 1874
on the Ship "Blackadder" Master White
Tonnage 908 Built at London When built 1870 - 2 mo.
By whom built Mandley Owners Mellis & Son
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 11854 Port of Leam Classed *A1

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Rivets</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stems	Pumps <u>2 in No</u>	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	Boats <u>4 (2 as life)</u>	<u>do</u>
Upper Deck Beams & Fastenings	<u>Firm</u>	Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings		<u>Ditto</u> ditto at other places	Sails <u>2 Suits</u>	<u>do</u>
Planksheers	<u>Good</u>	Keelsons	Anchors, No. of <u>3 B-1 S-2 K</u>	<u>do</u>
Sheerstrakes		Clamps and Shelves	Cables <u>Part seen</u>	<u>do</u>
Topsides		Ceiling	Hawsers and Warps	<u>Good & Sufficient</u>
Wales		Rudder	Standing and Running Rigging	
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>Now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

This vessel is now in a good and efficient Condition, eligible in my opinion to remain as Classed

Committee's Minute 23rd June 1874

Character assigned

L. Shilston

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18

Character assigned



© 2019

Lloyd's Register
Foundation
Certificate (if required).