

12881 ANNUAL SURVEYS.

Belgium

Mer 23/6/74

39 Sub^r No. 340 Survey held at Antwerp Date 12, 18 & 19 June 1874.
on the S.S. "Pauline David" late "Mad. Brussel" formerly "Emma, David," Master H. Yvaerts
Tonnage 1316 Built at Newcastle When built 1863. 10 mo.
By whom built Marshall Owners David Verhust & Co.
Port belonging to Antwerp Destined Voyage Antwerp - Black Sea
If Surveyed Afloat or in Dry Dock in Dry Dock

[Handwritten signature]

Last Survey, No. 10610 Port of Iron Classed A. 1.
The present Condition of the S. S. Blg. No. 972

Decks	good	Treenails	Rivets	good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of 3 Bower 1. Ar. 2. Tiedg.	
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	sufficient in size & length.
Topsides	Painted	Ceiling	"	"	Hawsers and Warps	good
Wales	"	Rudder	"	"	Standing and Running Rigging	good
Plank (Bottom) and Counter	"	Copper	Composition	When put on June 1874.		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good
This vessel was placed in Dry Dock on account of thinness, scraped from keel to loaden water-mark, the topsides painted with black lead and the bottom with Composition, she is at present in very good condition, fit for the conveyance of dry and perishable goods to and from all parts of the world and in my opinion worthy Committee's Minute 26th June 1874 to remain as classed.
Fees, Special £ 2.2.0
Change of Owners 1 " 7 June 1874
Certificate 5 " *[Signature]*
Character assigned *[Signature]* Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____



© 2019

Lloyd's Register
Foundation
Certificate (if required).