

769 No. 343 Survey held at Antwerp 12986 Date 20 & 21 July 1874.
 on the iron ship "Hillwall" Master Black
 Tonnage 1175 Built at London When built 1863. 10 mo
 By whom built Hillwall I.W.C. Owners Houghton, Smith & Co
 Port belonging to Liverpool Destined Voyage Antwerp - Cardiff.
 If Surveyed Afloat or in Dry Dock in dry Dock

Last Survey, No. 11291 Port of London Classed *A. 1.

The present Condition of the

Decks <u>good</u>	Treenails <u>rivets</u>	<u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>	Pumps <u>4</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>	Boats <u>4</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frames at the Openings <u>"</u>	<u>"</u>	Masts, Yards, &c. <u>Masts, mainmast, lower yards and topmast yards all of iron</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>	Sails <u>good</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>	Anchors, No. of <u>6</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>	Cables <u>300 fathoms</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>composition</u> When put on <u>July 1874</u>	<u>"</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Found in dry Dock and scraped from keel to head water-mark and then painted with composition, examined, keel, stem, stem-post, rudder, plating, rivets, keelsons, beams, frames, stringers and the whole equipment as far as practicable, and found all to be in a very good state and the ship eligible to her present class.

Committee's Minute 24th July 1874.

See's received
None

Character assigned TLW

Certificate (if required). no