

ANNUAL SURVEYS.

13025

Rev 20/7/74

No. 3320 Survey held at West Hartlepool Date 13th 16th July 1874
 on the S.S. "Memphis" Master B. Arncliffe
 Tonnage 1527 Built at Hartlepool When built 1872
 By whom built Withy Owners German Kaiser's Ship. Co.
 Port belonging to Hamburg Destined Voyage South America
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 11027 Port of Bron Classed 90 A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>3 + Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>not seen</u>	Boats <u>4 + Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Sails <u>Good</u>
Planksheers <u>Good</u>	Keelsons <u>not seen</u>	Anchors, No. of <u>3 Bowers 1 Stern 2 Pledges</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Cables <u>Good</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Hawsers and Warps <u>10-7 1/2-7-5-7-7-6-4 1/2 Good</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned down & coated with Paint. Propeller unscrewed & replaced with new.
Is now in a good & efficient state, fit for the safe conveyance of dry
& perishable goods to & from all parts of the World & may in my opinion remain
as now classed 90 A1

Committee's Minute 21st July 1874

Character assigned 90 A1

J. B. W.

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
Foundation

IRON458-0030