

13030
ANNUAL SURVEYS.

No. in Register 213
No. 1603 Survey held at Southampton Date 16 July 18 74
 on the Richmond S.S. Master John Edwards
 Tonnage 1080 Built at Middlesborough When built Nov 1871
 By whom built Bacchouse & Dixon Owners J. Dixon Junr
 Port belonging to London Destined Voyage Home & Mediterranean
☒ Surveyed Afloat ☐ in Dry Dock Code Flag W. D. G. Officer W. D. G.

Last Survey, No. 11436 Port of Iron Classed 90 A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Iron Gutters</u> <u>"</u>	Breasthooks <u>and Stems</u> <u>"</u>	Pumps <u>Iron 3 1/2" 6" Dia</u> <u>"</u>
Comings <u>Iron</u> <u>"</u>	Transoms, <u>Pointers</u> , and Crutches <u>"</u>	Boats <u>2 Life 2 1/2", Jolly 20, Gy 24 1/2"</u> <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	<u>Ditto</u> ditto at other places <u>"</u>	Sails <u>Sufficient &</u> <u>"</u>
Plank sheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B, 1 S, 2 K</u> <u>"</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>"</u>	Cables <u>240 Fathom 1 1/2" Dia</u> <u>"</u>
Topsides <u>"</u>	Ceiling <u>Good</u>	Hawsers and Warps <u>Sufficient & Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing and Running Rigging <u>Wool Hemp</u> <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Paint</u> When put on <u>7 May 1874</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

This vessel is lying in the Southampton docks partially laden with grain. I have examined her from the waterline to gunwale, below and in the fore and after compartments and part of the fore and main holds, and she appears to be in a very efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 21st July 18 74

Character assigned 90 A1

Edw Elliott Ld
 Fees received 1-1-0

Certificate (if required). 5-0

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Plank sheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 ____

Character assigned _____