

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. No. 24264 Survey held at Liverpool Date, first Survey 11th July Last Survey 14 July 1874
 on the Iron S.S. "Thames" Master J. J. Jones
 Tonnage 3835 built at Newcastle When built 1873-10 mo
 By whom built Palmer & Co Owners E. & W. Mills & W. Milburn
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat in open dock
 Last Survey, No. 12370 Port IRON Classed 100A1

REPAIRS, &c.

Through damage sustained by collision
 5 plates new on each bow. 2 frames scarpes on the
 Starboard side and three on the Port side. 2 plates
 temporarily repaired

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stems <u>Good</u>	Pumps <u>Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Good</u>
Planksheers <u>Good</u>	Keelsons <u>Good</u>	Sails <u>Good</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>Good</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Cables <u>Good</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>Good</u>	Standing & Running Rigging <u>Good</u>
Engine Room Skylights <u>Good</u>	Caulking of <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	Hatches <u>Good</u>
Scuppers <u>Good</u>	Good	

General Observations and Opinion,

As far as seen she is now in good condition and in
 my opinion may continue as classed

The Amount of Entry Fee.....£ 3 : " : " is received by me,

Special..... 2 : 2 - 20/7/74

Certificate (if required) " : " : "

Committee's Minute Liverpool 31st July 1874

Character assigned 100A1 Damage Repair
 Special on Damage to 5-5-5-5 20/7/74



© 2019
 Lloyd's Register
 Foundation

"Whampoa" 24264



© 2019

Lloyd's Register
Foundation