

ANNUAL SURVEYS.

34060
13157

44 No. 159 Survey held at London Date Aug 7th 18 74
on the S.S. "Tanfield" Master G. Bowdell
Tonnage 587 Built at Newcastle When built 1864 — 12 mo.
By whom built Palmer Owners Cory & Co
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Lincolns Dry Dock

Last Survey, No. 11694 Port of London

Classed A1
S.S. Lon No. 3. 73. 7. 73.

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>2 pumps</u> <u>do</u>
Comings	} <u>Form</u>	Transoms, Pointers, and Crutches	} <u>Good</u>	Boats	<u>3 in No</u> <u>do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	} <u>Good</u>	Ditto ditto at other places	} <u>Good</u>	Sails	<u>full suit</u> <u>do</u>
Planksheers		Keelsons		Anchors, No. of	<u>good</u>
Sheerstrakes	} <u>Good</u>	Clamps and Shells	} <u>and</u>	Cables	<u>sufficient</u>
Topsides		Ceiling		Hawsers and Warps	<u>sufficient</u>
Wales	} <u>Good</u>	Rudder	} <u>sufficient</u>	Standing and Running Rigging	<u>sufficient</u>
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>Now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good.

A few butts caulked, bottom cleaned and painted, she is now in a good and efficient condition, eligible in my opinion to remain as classed A1.

J. Shilston.

Committee's Minute 21st August 18 74

Character assigned A1

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register
Foundation
Certificate (if required).