

ANNUAL SURVEYS.

No. 274 Survey held at London Date Aug 12th 18 74
 on the Iron Ship. Phidias Master Peters
 Tonnage 997 Built at Lumbarton When built 1869. 9 mo.
 By whom built McMillan Owners Shaw Savill & Co.
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock

Last Survey, No. 11868 Port of London Classed A. I
 The present Condition of the Good SS. London No. 1. 73. 9. 73
 Decks Good Treenails Pivots where seen Good Windlass and Capstan Good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats 5
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3 B. 1. 2 K.
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawser and Warps "
 Wales " Rudder " Standing and Running Rigging "
 Plank (Bottom) and Counter " Copper Paint When put on Now
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
Bottom Scraped & painted New rudder Bush.
She is now in good condition. Eligible in
our opinion to remain as Classed
 Committee's Minute 21st August 1874
 Character assigned A. I WS
 James Mollison
 Senior Mastermate
 Certificate (if required).

No. 838 Survey held at London Date Aug 12th 18 74
 on the Iron Ship. Asaye Master McMichee
 Tonnage 1281 Built at Greenock When built 1868 - 8 mo.
 By whom built Steele Owners J. W. Stewart
 Port belonging to Greenock Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 11877 Port of London Classed A. I
 The present Condition of the Good SS. Glyde No. 1. 73 8. 73
 Decks Good Treenails Pivots where seen Good Windlass and Capstan Good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats 5
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors, No. of 3 B. 1. 2 K.
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawser and Warps "
 Wales " Rudder " Standing and Running Rigging "
 Plank (Bottom) and Counter " Copper Paint When put on Now
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
Bottom Scraped & painted. She is in good
condition Eligible in our opinion to
remain as Classed
 Committee's Minute 21st August 1874
 Character assigned A. I WS
 James Mollison
 Senior Mastermate
 Certificate (if required).