

ANNUAL SURVEYS.

13243
 No. 560 Survey held at London Date Feb^r 8th 10th 1874
 on the Iron Ship Childers Master J. Efford
 Tonnage 896 Built at Sunderland When built 1868 8 mo.
 By whom built Doxford Owners Hughes & Co.
 Port belonging to Liverpool Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Union dry dock V

Last Survey, No. 11310 Port of Liverpool Classed A.1. S.S. No 1/73
 3.73

The present Condition of the

Decks	<u>good</u>	Freeboards	<u>Rivets where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of <u>3 B. 1 S. 2 K.</u>	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	<u>When put on</u>	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Survey'd with some cargo on board. - Bottom very foul. Cleaned and recoated with Mc Ginnip's composition. Overhauled and made good the Rudder and all in connection with the steering apparatus. - She is in good condition, and in my opinion she is entitled to remain as classed A.1.

Committee's Minute 2nd October 1874

Character assigned

Certificate (if required).

No. 904 Survey held at London Date Feb^r 14th 22nd 1874
 on the Iron Barque Merle Master J. Wills
 Tonnage 281 Built at London When built 1863 11 mo.
 By whom built Westwood Owners Scrutton Sons & Co.
 Port belonging to London Destined Voyage W. Indies
 If Surveyed Afloat or in Dry Dock Union dry dock & West India docks

Last Survey, No. 12771 Port of Liverpool Classed A.1. S.S. No 2/72
 5.74

The present Condition of the

Decks	<u>good</u>	Freeboards	<u>Rivets where seen</u>	<u>good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	
Planksheers	"	Keelsons	"	"	Anchors, No. of	
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	
Topsides	"	Ceiling	"	"	Hawsers and Warps	
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	
Plank (Bottom) and Counter	"	Copper	<u>When put on</u>	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Cleaned the bottom, and recoated it with Coal tar, and Naphtha. Cleaned her out inside. - She is in good condition and is in my opinion entitled to remain as classed A.1.

Committee's Minute 2nd October 1874

Character assigned

Certificate (if required).

Children's Market



© 2019

Lloyd's Register
Foundation