

ANNUAL SURVEYS.

No. in Reg. Book. **No.** 13280 Survey held at London Date, first Survey Aug 31st Last Survey Oct 1st 1874
 on the Iron S. Saint Magnus Master Sutherland
 Tonnage 1262 Built at Liverpool When built 1867-June
 By whom built Royden Owners Rankin & Co
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11716 Port of Liverpool Classed AI 8.73
 Present Condition of the Decks at present the bottom coated and Painted (Scraped) s.s. Cey No 1-72
 Waterways Good Treenails Rivets Good
 Comings do Breasthooks and Stemson do
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Planksheers Plating do Ditto ditto at other places do
 Sheerstrakes do do Keelsons do
 Topsides do do Clamps and Shelves do
 Wales do do Ceiling do
 Plank (Bottom) and Counter do do Rudder do
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Copper or Y.M. do When put on do
 General Observations, Opinion as to Class, &c. do Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan do
 Pumps do
 Boats 4
 Masts, Yards, &c. Good
 Condition, how ascertained and
 Sails sufficient
 Anchors, No. of 3 B. & 1 Redg where
 Cables they could
 Hawseers and Warps be seen
 Standing and Running Rigging do
 Scuppers Good Cargo and Main Hatchways Good Hatches Good

She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Committee's Minute 13th October 1874 Senhouse Martindale
 Character assigned AI ITW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1874

No. in Reg. Book. **No.** 13280 Survey held at London Date, first Survey Aug 18 Last Survey 18
 on the Iron S. Star of Denmark Master Wayne
 Tonnage 258 Built at Belfast When built 1863 G.M.
 By whom built Harland Owners Cory & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11993 Port of Liverpool Classed AI 11.73
 Present Condition of the Decks at present the bottom Scraped and Painted s.s. Cey No 2-73
 Waterways Good Treenails Rivets Good
 Comings do Breasthooks and Stemson do
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Planksheers Plating do Ditto ditto at other places do
 Sheerstrakes do do Keelsons do
 Topsides do do Clamps and Shelves do
 Wales do do Ceiling do
 Plank (Bottom) and Counter do do Rudder do
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Copper or Y.M. do When put on do
 General Observations, Opinion as to Class, &c. do Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan do
 Pumps do
 Boats 4
 Masts, Yards, &c. Good
 Condition, how ascertained sufficient
 Sails where
 Anchors, No. of 3 B. & 1 Redg they
 Cables could be
 Hawseers and Warps seen
 Standing and Running Rigging do
 Scuppers Good Cargo and Main Hatchways do Hatches do

She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Committee's Minute 13th October 1874 Senhouse Martindale
 Character assigned AI ITW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1874