

# ANNUAL SURVEYS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Sept 21 Last Survey 1874  
 on the Iron Ship Hudson Master Irmen  
 Tonnage 788 Built at Stockton When built 1865 3M.  
 By whom built Pearse Owners Shaw Saville & Co.  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 12008 Port of London

Classed X/A Years assigned. 11.73 Character in Register Book. SS Lon M-73

Present Condition of the  
 Decks Good Treennails Pivots Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers Plating do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

at present the bottom scraped painted and coated  
 She is now in an efficient state of repair and  
 in my opinion entitled to remain as classed

Committee's Minute 13<sup>th</sup> October 1874 Senhouse Martinide  
 Character assigned X/A JPM Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) do Paid do 1874

No. in Reg. Book. **No.** Survey held at London Date, first Survey Sept 7 Last Survey Sept 11<sup>th</sup> 1874  
 on the Iron S City of Vienna Master Macdonald  
 Tonnage 1000 Built at Glasgow When built 1866 3M.  
 By whom built Cornell Owners Smith & Co.  
 Port belonging to Glasgow Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 11981 Port of London

Classed X/A Years assigned. 11.72 Character in Register Book. SS Lon M-70

Present Condition of the  
 Decks Good Treennails Pivots Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers Plating do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

at present the bottom scraped painted and coated  
 She is in an efficient state of repair and in my  
 opinion entitled to remain as classed

Committee's Minute 13<sup>th</sup> October 1874 Senhouse Martinide  
 Character assigned X/A JPM Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) do Paid do 1874