

(Iron)

13370
ANNUAL SURVEYS.

34128

No. 901 Survey held at London Date Sep 9th - 11th 1874
on the Ship Star of Germany Master Wilson
Tonnage 1337 Built at Belfast When built 1872-3 mo
By whom built Harland Owners Cory & Son
Port belonging to Belfast Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Wyrams Dry Dock

Recd 22-9-74

Last Survey, No. 12010 Port of Iron Classed 100 A.1
11.73

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	Where
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	Seen
Plank sheers	"	Keelsons	"	"	Anchors, No. of 3 1/2 1 1/2 2 1/2	Good
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	Efficient
Wales	"	Rudder	"	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good & Efficient

Bottom scraped & painted, bilges cleaned & cement repaired where worn, she is entitled to remain as classed.

Committee's Minute 25th September 1874

Character assigned 100 A.1

James Morrison
Surveyor General
Certificate (if required).

JRM

No. 91 Survey held at London Date Sep 1st - 3rd 1874
on the Ship Lady Jocelyn (Iron) Master G. Jenkins
Tonnage 2138 Built at London When built 1852
By whom built Mare Owners Park Brothers
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock James Son Work. Dry Dock

Last Survey, No. 11644 Port of Iron Classed A.1
S.S. No. 1-71 4.73

The present Condition of the

Decks	Good	Treenails	Rivets where seen	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	Where
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	Seen
Plank sheers	"	Keelsons	"	"	Anchors, No. of 3 1/2 1 1/2 2 1/2	Good
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	Efficient
Wales	"	Rudder	"	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom scraped & painted, rudder examined, bilges cleaned & cement repaired.

She is entitled to remain as classed

Committee's Minute 25th September 1874

Character assigned A.1

James Morrison
Surveyor General
Certificate (if required).

JRM