

# ANNUAL SURVEYS.

No. 1137 Survey held at Liverpool Date 16<sup>th</sup> to 19<sup>th</sup> Oct 1874  
 on the 20<sup>th</sup> Bk Archibald Fuller Master E. Kite  
 Tonnage 700 Built at Liverpool When built 1868-11 mo  
 By whom built Quans Owners St. Loghell  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Running dry Dk

Last Survey, No. 12075 Port of Liverpool Classed \*A 1 73  
S.S. Liverpool

The present Condition of the

Decks	Good	Transoms	Rivets	Good	Windlass and Capstan	Good
Waterways	—	Breasthooks and Stems	—	—	Pumps	—
Comings	—	Transoms, Pointers, and Crutches	—	—	Boats	—
Upper Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—	—	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	—	Ditto ditto at other places	—	—	Sails	—
Planksheers	—	Keelsons	—	—	Anchors, No. of <u>3 B. 1 S. &amp; 2 K</u>	—
Sheerstrakes	—	Clamps and Shelves	—	—	Cables <u>part seen</u> Good	—
Topsides	—	Ceiling	—	—	Hawsers and Warps	—
Wales	—	Rudder	—	—	Standing and Running Rigging	—
Bottom (Bottom) and Counter	—	Copper <u>Tinnet</u> When put on <u>1868</u>	—	—		—

General Observations and Opinion, Bottom painted - Rudder hanging repaired. She is now in good condition and in my opinion may continue as Classed

Committee's Minute Liverpool, 3<sup>rd</sup> November, 1874. Wm. C. Davy

Character assigned \*A 1

Certificate (if required).

No. 10586 Survey held at Liverpool Date 10<sup>th</sup> to 13<sup>th</sup> Oct 1874  
 on the 20<sup>th</sup> Bk Broughton Master J. Branthwaite  
 Tonnage 580 Built at Belfast When built 1868-1 mo  
 By whom built Harland Owners May & Co  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Running dry dock

Last Survey, No. 10586 Port of Liverpool Classed \*A 1 73  
S.S. Liverpool

The present Condition of the

Decks	Good	Transoms	Rivets	Good	Windlass and Capstan	Good
Waterways	—	Breasthooks and Stems	—	—	Pumps	—
Comings	—	Transoms, Pointers, and Crutches	—	—	Boats	—
Upper Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—	—	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	—	Ditto ditto at other places	—	—	Sails	—
Planksheers	—	Keelsons	—	—	Anchors, No. of <u>3 B. 1 S. &amp; 2 K</u>	—
Sheerstrakes	—	Clamps and Shelves	—	—	Cables <u>part seen</u> Good	—
Topsides	—	Ceiling	—	—	Hawsers and Warps	—
Wales	—	Rudder	—	—	Standing and Running Rigging	—
Bottom (Bottom) and Counter	—	Copper <u>Tinnet</u> When put on <u>1868</u>	—	—		—

General Observations and Opinion, Bottom painted - Rudder painted broken. She is in good condition and in my opinion may continue as Classed

Committee's Minute Liverpool, 3<sup>rd</sup> November, 1874. Wm. C. Davy

Character assigned \*A 1

Certificate (if required).



"Archibald Miller"

"Broughton" 24346



© 2019

Lloyd's Register  
Foundation