

ANNUAL SURVEYS.

No. in Reg. Book. **No.** 91 Survey held at London Date, first Survey Sept 25 Last Survey Sept 30th 1874
 on the Iron S Eblana Master Lever
 Tonnage 1351 Built at Birkenhead When built 1864 7 M^o
 By whom built Laid Owners Brooke & Co
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 10210 Port of Iron
 Present Condition of the Decks at present the bottom scraped painted & coated
 Decks good Treennails good Rivets good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers Plating Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. When put on do
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. She is now in an efficient state of repair and in my opinion entitled to remain as classed

Committee's Minute 16th October 1874
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **No.** 328 Survey held at London Date, first Survey Aug 28th Last Survey 18
 on the Iron S Glenavon Master Smith
 Tonnage 1080 Built at Lumbarton When built 1868 6 M^o
 By whom built Mc Millan Owners Gow & Co
 Port belonging to Glasgow Destined Voyage Not known
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11663 Port of Iron
 Present Condition of the Decks at present the bottom scraped painted & coated
 Decks good Treennails good Rivets good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers Plating Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. When put on do
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. She is now in a good state of repair and in my opinion entitled to remain as classed

Committee's Minute 16th October 1874
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18