

13456

REPORT of SURVEY for REPAIRS.

Recd 11/11/74

N^o in Reg. Book No. 1045 Survey held at Dublin Date 5th Nov 1874
388 on the SS Goyle Master D Galepue
 Tonnage 199 Built at Newcastle When built 1872 10th mo
 By whom built John Owners M W Chrystal
 Port belonging to Londonderry Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock in dry dock & afloat

Last Survey, No. 13453 Port Dublin Iron Classed 90 A 1 10.73

REPAIRS

This vessel was reported on Annual Survey of 8th ult
 (See official N^o 81)

Having been since in Collision, the owner has called on me, being desirous to have the repairs now done (which are trifling) reported to Lloyd's Committee, in compliance with his request, I beg leave to state, that, on the Starboard Bow one Sheer Strake Plate and one Bulwark Plate has been renewed and also two pieces of Gunwale Angle Iron - likewise about 15 feet of Rail with warping Chock and six Stanchions

Present Condition of these are to be found in Survey Report of 8th ult

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways.

I consider this vessel, is now in as efficient a state of and good a state of Repair, as when surveyed on 8th ult and is fit to retain her Character as Classed

The Amount of Fee.....£ : : is received by me,

Surveyors fee Special..... 1 : 1 : 0

Mr W M Certificate (if required) : :

Committee's Minute 13th November 1874

Character assigned 90 A 1

Drp 74

14/11/74

JFW

24 Dec 74
 13/11/74



© 2019

Lloyd's Register
Foundation

IRON 459-0076