

# ANNUAL SURVEYS.

No. 238 Survey held at London Date Feb<sup>y</sup> 21<sup>st</sup> Oct<sup>r</sup> 10<sup>th</sup> 1874  
 on the Sun Screen Steamer Hector Master John Sax  
 Tonnage 1986 Built at Sunderland When built 1863. 4 mo  
 By whom built Saing Owners Gowley & Co.  
 Port belonging to Sunderland Destined Voyage ✓  
 If Surveyed Afloat or in Dry Dock Britannia dry dock & Mill wall afloat

Last Survey, No. 12.223 Port of London Classed 90. A. 1. S.S. No 2/21

The present Condition of the

Decks	<u>good</u>	Freemasts	<u>Rivers where seen good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Sails	<u>"</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Anchors, No. of	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps	<u>"</u>
Wales	<u>"</u>	Rudder	<u>efficient</u>	Standing and Running Rigging	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper	<u>When put on</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Cleaned the bottom, and recoated it. She is in good condition and I am of opinion she is entitled to remain as Classd 90. A. 1.

Committee's Minute 30<sup>th</sup> October 1874

Character assigned 90A

Certificate (if required).

IRON459-0093

2: 11 1/2  
Sector K  
Neptuno



© 2019

Lloyd's Register  
Foundation