

13652

REPORT of SURVEY for REPAIRS, &c.

No. in
Reg. Book.

No. 3375

Survey held at West Hartlepool Date, first Survey

Last Survey 11th November 1874

on the

S.S. "Helle"

Master

W. Todd

Tonnage

395
611 6
542

built at

West Hartlepool

When built

1871. 1 mo

By whom built

Denton

Owners

J. Pyman & Co.

Port belonging to

West Hartlepool

Destined Voyage

Klenburg

If Surveyed Afloat or in Dry Dock

In Dry Dock

Last Survey, No.

12044

Port

Iron

Classed

90 A1

Years assigned.

Character in Register Book.

10. 73

REPAIRS, OR EXAMINATION AS PER RULE

Survey No. 1 Iron Ship.

Limber boards taken up, man hole covers taken off of water ballast tanks, Scraped clean inside & out all found firm & good, cement on flat made up where necessary, vessel coated outside with Paint & Black barnish & part inside with Paint.

Present Condition of the

Decks

Good

Waterways

Good

Conings

Good

Upper Deck Beams & Fastenings

Good

Lower Deck Beams & Fastenings

Good

Panksheers

Good

Skerstrakes

Good

Tipsides

Good

Vales

Good

Bottom (Bottom) and Counter

Good

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

Good

General Observations, Opinion as to Class, &c.

Has not been specially surveyed under the Rules Survey

No. 1 for Iron Ships, is now in a good & efficient state fit for the safe carriage of dry & perishable goods to & from all parts of the World & in my opinion remains classed 90 A1
S.S. Helle No. 1-74

The Amount of Entry Fee ...

... £ ...

received by me, }

19th 1874

Special

... £ 4 : 4 : -

Certificate (if required) ...

... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

24th November 1874

Character assigned

90 A1

S.S. Helle No. 1-74

T.B.W.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 459-0324