

(Iron)

ANNUAL SURVEYS.

No. in Reg. Book. **No.** 144 on the **Scout Kingston** Survey held at **London** Date, first Survey **Nov 13th** Last Survey **Nov 14th** 1874
Master **R. Chisham**
Tonnage **930** Built at **Sunderland** When built **1871** - **2 mo.**
By whom built **Ward** Owners **Mutual Steam Ship Co.**
Port belonging to **London** Destined Voyage **Mediterranean**
If Surveyed Afloat or in Dry Dock **Limskiln Dry Dock**

Last Survey, No. **12711** Port of **London** Classed **90 A1.**
Present Condition of the Decks **Good** **Treenails Rivets**
Waterways **Good** **Breasthooks and Stems**
Comings **Good** **Transoms, Pointers, and Crutches**
Upper Deck Beams & Fastenings **Good** **Timbers of the Frame at the Openings**
Lower Deck Beams & Fastenings **Good** **Ditto ditto at other places**
Planksheers **Good** **Keelsons part seen**
Sheerstrakes **Good** **Clamps and Shelves**
Topsides **Good** **Ceiling part seen**
Wales **Good** **Rudder**
Plank (Bottom) and Counter **Good** **Copper or Y.M. paint When put on Now**
Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c. **Good**

Bottom sighted & coated with N. Lead & tallow. Vessel is in a good and efficient condition, and eligible in my opinion to remain as classed 90 A1.

Committee's Minute **1st January** 1875 **T. Shilston**
Character assigned **90 A1** **T. Shilston** Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **T. Shilston** Paid **18**

No. **No.** Survey held at **Date, first Survey** **Last Survey** 18
Reg. Book. on the **Master**
Tonnage **Built at** **When built**
By whom built **Owners**
Port belonging to **Destined Voyage**
If Surveyed Afloat or in Dry Dock

Last Survey, No. **Port of** **Classed**
Present Condition of the Decks **Treenails**
Waterways **Breasthooks and Stems**
Comings **Transoms, Pointers, and Crutches**
Upper Deck Beams & Fastenings **Timbers of the Frame at the Openings**
Lower Deck Beams & Fastenings **Ditto ditto at other places**
Planksheers **Keelsons**
Sheerstrakes **Clamps and Shelves**
Topsides **Ceiling**
Wales **Rudder**
Plank (Bottom) and Counter **Copper or Y.M. When put on**
Engine Room Skylights **Coal Bunkers, Openings, Lids, &c.** Scuppers **Cargo and Main Hatchways** Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute **18**
Character assigned **Surveyor to Lloyd's Register of British and Foreign Shipping.**
Certificate (if required) **Paid** **18**



© 2019

Lloyd's Register Foundation

IRON 460-0002