

ANNUAL SURVEYS.

13827
 No. in Register Book **1045** No. **87** Survey held at **Dublin** Date **28th January** 18**75**
 on the **SS Coreyra** Master **Beaton**
 Tonnage **724** Built at **Hockton** When built **1862 (7 mo)**
 By whom built **Richardson** Owners **Messrs Pelgrave & Co**
 Port belonging to **Dublin** Destined Voyage **Holland**
 If Surveyed Afloat or in Dry Dock **In Dry Dock**

Last Survey, No. **10710** Port of **Dublin**

Classed **A1** ^{ms} **9.72**
 S.S. Dub No. **2.72**

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

This vessel has now been placed in dry dock, where she has undergone a thorough overhaul - the bottom has been scraped clean and painted - I now consider her in a good & efficient condition & in my opinion is entitled to retain her Character as Classed

Committee's Minute **9th February** 18**75**

Character assigned

Survey fee **£1.1.0** Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Committee's Minute _____ 18____

Character assigned