

Iron

13860  
ANNUAL SURVEYS.

No. in Reg. Book. 186 No. 186 Survey held at London Date, first Survey Feb 3<sup>rd</sup> Last Survey Feb 5<sup>th</sup> 1875  
on the Ship Oriana Master W. Guthrie  
Tonnage 997 Built at Greenock When built 1864 - 2 mo  
By whom built Scott Owners W. Orr  
Port belonging to Greenock Destined Voyage New Zealand  
If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 9958 Port of London Classed S.S. Low No 2 Years assigned. 72 Character in Register Book. \*A1  
Present Condition of the Decks Good Treenails Pivots Good  
Waterways ✓ Breasthooks and Stemson ✓  
Comings ✓ Transoms, Pointers, and Crutches ✓  
Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓  
Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓  
Planksheers ✓ Keelsons part seen  
Sheerstrakes ✓ Clamps and Shells ✓  
Topsides ✓ Ceiling part seen  
Wales ✓ Rudder ✓  
Plank (Bottom) and Counter ✓ Copper or Y.M. Paint When put on Now  
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Bottom sighted, cleaned & coated with Vivian's patent Composition - She is now in a good and efficient condition, eligible in my opinion to remain as Classed

Committee's Minute Feb 9<sup>th</sup> 1875 T. Shilston  
Character assigned ✓ Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) ✓ Paid ✓ 1875

No. 186 Survey held at London Date, first Survey Feb 3<sup>rd</sup> Last Survey Feb 5<sup>th</sup> 1875  
No. in Reg. Book. 186 on the Ship Oriana Master W. Guthrie  
Tonnage 997 Built at Greenock When built 1864  
By whom built Scott Owners W. Orr  
Port belonging to Greenock Destined Voyage New Zealand  
If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 9958 Port of London Classed S.S. Low No 2 Years assigned. 72 Character in Register Book. \*A1  
Present Condition of the Decks Good Treenails Pivots Good  
Waterways ✓ Breasthooks and Stemson ✓  
Comings ✓ Transoms, Pointers, and Crutches ✓  
Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓  
Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓  
Planksheers ✓ Keelsons part seen  
Sheerstrakes ✓ Clamps and Shells ✓  
Topsides ✓ Ceiling part seen  
Wales ✓ Rudder ✓  
Plank (Bottom) and Counter ✓ Copper or Y.M. Paint When put on Now  
Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Bottom sighted, cleaned & coated with Vivian's patent Composition - She is now in a good and efficient condition, eligible in my opinion to remain as Classed

Committee's Minute Feb 9<sup>th</sup> 1875 T. Shilston  
Character assigned ✓ Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) ✓ Paid ✓ 1875