

ANNUAL SURVEYS.

13910

Read 6. 2. 75

No. in Reg. Book. **No.** 765 Survey held at **London** Date, first Survey **Feb 2nd** Last Survey **Feb 5th** 18**75**
 on the **Sewer "Maud"** Master **F. Brittain**
 Tonnage **843** Built at **West Hartlepool** When built **1871 - 12 mo**
 By whom built **Nulton** Owners **Marwood & S.**
 Port belonging to **Whitby** Destined Voyage **Not known**
 If Surveyed Afloat or in Dry Dock **Wigrams Dry Dock**

Last Survey, No. **13796** Port of **London** Classed **100 Al.** Years assigned. **12-74** Character in Register Book.
 Present Condition of the Decks **Good**
 Waterways **Good** Treennails **Good**
 Comings **Good** Breasthooks and Stenson **Good**
 Upper Deck Beams & Fastenings **Good** Transoms, Pointers, and Crutches **Good**
 Lower Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Planksheers **Good** Ditto ditto at other places **Good**
 Sheerstrakes **Good** Keelsons **part seen**
 Topsides **Good** Clamps and Shelves **Good**
 Wales **Good** Ceiling **part seen**
 Plank (Bottom) and Counter **Good** Rudder **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Good**

Bottom sighted, paint chafed off bottom, from having been in the ice, on her voyage from the Baltic, bottom now coated with paint and tallow. She is in a good & efficient condition eligible in my opinion to remain as classed -

Committee's Minute **Feb 9th** 18**75** **T. Shilston**
 Character assigned **100 A** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. in Reg. Book. **No.** Survey held at Date, first Survey Last Survey 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.
 Present Condition of the Decks
 Waterways Treennails
 Comings Breasthooks and Stenson
 Upper Deck Beams & Fastenings Transoms, Pointers, and Crutches
 Lower Deck Beams & Fastenings Timbers of the Frame at the Openings
 Planksheers Ditto ditto at other places
 Sheerstrakes Keelsons
 Topsides Clamps and Shelves
 Wales Ceiling
 Plank (Bottom) and Counter Rudder
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute **Feb 9th** 18**75**
 Character assigned **100 A** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18