

ANNUAL SURVEYS.

No. in Reg. Book. **No.** 128 Survey held at **London** Date, first Survey **Mar 2nd** Last Survey **Mar 8th** 1875
 on the **Iron Ship Lady Palmerston** Master **Mills**
 Tonnage **1247** Built at **Greenwich** When built **1864**
 By whom built **Stule** Owners **Lanworth & Co**
 Port belonging to **Liverpool** Destined Voyage **Calcutta**
 If Surveyed Afloat or in Dry Dock **Dockyard Victoria Dock**

Last Survey, No. **10832** Port of **London** Classed ***A1** 11-1/2
 Present Condition of the Decks **at present Bottom scraped, painted & coated**
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Plating** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Rudder **Good**
 Copper or Y.M. Paint When put on **Good**
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **Good**
 Sails **Good**
 Anchors, No. of **3 Bows 1 1/2 Rode**
 Cables **Good**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **She is in an efficient state of repair and in our opinion eligible to remain as classed.**

Committee's Minute **12th March** 1875
 Character assigned ***A1**

Senhouse Martindale
James Wain
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **No.** 716 Survey held at **London** Date, first Survey **July 12** Last Survey **July 12** 1875
 on the **Iron S. Star of Persia** Master **Corry**
 Tonnage **1227** Built at **Belfast** When built **1868**
 By whom built **Harland** Owners **Corry & Co**
 Port belonging to **Belfast** Destined Voyage **Calcutta**
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **12885** Port of **London** Classed ***A1** 6.74
 Present Condition of the Decks **at present Bottom scraped, painted & coated**
 Waterways **Good** Breasthooks and Stemson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Plating** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shelves **Good**
 Topsides **Good** Ceiling **Good**
 Rudder **Good**
 Copper or Y.M. Paint When put on **Good**
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **Good**
 Sails **Good**
 Anchors, No. of **3 Bows 1 1/2 Rode**
 Cables **Good**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **She is now in an efficient state of repair and in my opinion entitled to remain as classed.**

Committee's Minute **12th March** 1875
 Character assigned ***A1**

Senhouse Martindale
James Wain
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18