

14053

35504

Iron

REPORT of SURVEY for REPAIRS, &c.

Recd. 2. 3. 75

No. in Reg. Book. **No.** Survey held at London Date, first Survey Feb'y 15th Last Survey Feb'y 24th 18 75
760 on the U. B. Matthew Bay Master J. Bradley
 Tonnage 276 built at V. Shields When built 1872. 11
 By whom built L. P. Lottley Owners Hall & Co
 Port belonging to V. Shields Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Princes Dry Dock.

Last Survey, No. 13507 Port Iron Classed 90 A 1
 10-74

REPAIRS, OR EXAMINATION AS PER RULE Damage Repairs &c.
Socked on blocks, a number of Ribs in after
plate of garboard strake on Starboard side found to be
started, the plate taken out, and the cement removed,
a new plate fitted, riveted, and caulked, and the cement
renewed inside, bottom cleaned and coated with
Patent Composition and the topsides with paint.

Cause of Repairs to be clearly stated.

Present Condition of the				
Decks	<u>Good</u>	<u>Ribs</u>	<u>Good</u>	Windlass and Capstan
Waterways	<u>"</u>	<u>Greenails</u>	<u>"</u>	Pumps
Comings	<u>"</u>	Breasthooks and Stems	<u>"</u>	Boats
Upper Deck Beams & Fastenings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Condition, how ascertained <u>When from decks</u>
Planksheers	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Sails
Sheerstrakes	<u>"</u>	Keelsons	<u>"</u>	Anchors No. of <u>3 1/2 18th 3 1/2</u>
Topsides	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables
Wales	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps
Plank (Bottom) and Counter	<u>"</u>	Rudder	<u>"</u>	Standing & Running Rigging
Engine Room Skylights	<u>Good</u>	Copper <u>Cem</u> When put on <u>1872</u>		
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Caulking of		
Scuppers	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>	
Cargo and Main Hatchways	<u>Good</u>			
Hatches	<u>Good</u>			
General Observations, Opinion as to Class, &c. <u>She is now in good and efficient</u> <u>condition, and eligible to remain as classed: viz-</u> <u>90 A 1.</u>				

The Amount of Entry Fee £ : :
 Special £ 2 : 2
 Certificate (if required) £ : 5

(Travelling Expenses, if any, £ _____)

Committee's Minute 12th March 18 75Character assigned 90 A 1

received by me,

10. 3. 1875

Thomas W. Blayell

Wm. L. Davey

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

RON 460-0324