

ANNUAL SURVEYS.

Rev 22/3/75

No. 3441 Survey held at Newport Date 9th March 1875
 on the Iron Ship "Dera" Master Challen
 Tonnage 798 1/2 Built at Liverpool When built 1843 5th M^{rs}
 By whom built Royden Owners Valmley (Liverpool)
 Port belonging to Liverpool Destined Voyage S. America
 If Surveyed Afloat or in Dry Dock Newport Dry Dock

Last Survey, No. 11805 Port of Liverpool Classed 100 M.S.

8.73

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Plenty</u>	Windlass and Capstan	
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Sails	
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Anchors, No. of	
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables	
Topsides	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps	
Wales	<u>"</u>	Rudder	<u>"</u>	Standing and Running Rigging	
Plank (Bottom) and Counter	<u>"</u>	Copper	<u>Paint</u> When put on <u>Nov</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks in Dry Dock. Bottom cleaned and coated with Patent Paint - She appears in very good condition, eligible to remain as Classed 100 M.S.

Committee's Minute 23rd March 1875

Freemantle S.I. 1. 0

Character assigned 100A

J.W. Henry J. Lynell

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register Foundation
 Certificate (if required).

217111 *Dever* 111111



© 2019

Lloyd's Register
Foundation