

ANNUAL SURVEYS.

Recd. 2.4.75

No. in **No.** Survey held at London Date, first Survey March 18th Last Survey April 2nd 1875
 Reg. Book. on the Iron Barque Lady Douglas Master Alfred Wymark
~~5469~~ 63 Tonnage 594 Built at Greenock When built 1856
 By whom built Scott Owners Taylor, Bethell, & Roberts
 Port belonging to London Destined Voyage Rockhampton
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 12343 Port of London Classed S.S. Div No. 3-72 Character in Register Book *A 1 2-74

Present Condition of the Decks <u>good</u>	<u>Rivets</u> Treenails <u>good</u>	
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Windlass and Capstan <u>good</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Pumps <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Boats <u>Four</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Masts, Yards, &c. <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Condition, how ascertained <u>from deck</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Sails <u>* well found</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Anchors, No. of <u>3 Bower, 2 Hedges & stream</u>
Wales <u>"</u>	Rudder <u>"</u>	Cables <u>240 fathoms</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>"</u> When put on <u>"</u>	Hawsers and Warps <u>Complete</u>
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>"</u>	Standing and Running Rigging <u>Sufficient</u>
Coal Bunker, Openings, Lids, &c. <u>"</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u> Hatches <u>good</u>

General Observations, Opinion as to Class, &c. Ship put in dry dock, bottom scraped and painted

Committee's Minute 6th April 1875 William Allison
 Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Character in Register Book _____

Present Condition of the Decks _____	<u>Treenails</u>	
Waterways _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Comings _____	Transoms, Pointers, and Crutches _____	Pumps _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Boats _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Planksheers _____	Keelsons _____	Condition, how ascertained _____
Sheerstrakes _____	Clamps and Shelves _____	Sails _____
Topsides _____	Ceiling _____	Anchors, No. of _____
Wales _____	Rudder _____	Cables _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Hawsers and Warps _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Standing and Running Rigging _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

