

14235 ANNUAL SURVEYS.

No. in Reg. Book. **652** No. **1043** Survey held at **London** Date, first Survey **1st April 1875** Last Survey **27th April 1875**
 on the **Iron Ship City of Agra** Master **Living**
 Tonnage **1043** Built at **West Hartlepool** When built **1860 - 9th Mo.**
 By whom built **Pile** Owners **Coupland Bros.**
 Port belonging to **Liverpool** Destined Voyage **Australia**
 If Surveyed Afloat or in Dry Dock **By Dock & Afloat**

Last Survey, No. **12374** Port of **London** Classed ***A** Years assigned **3. 1/4** Character in Register Book **S.S. Gen. 803-1/4**
 Present Condition of the Decks **Good** **Freemasts** **Stretts** **Good**
 Waterways **"** Breasthooks and Stenson **"** Windlass and Capstan **"**
 Comings **"** Transoms, Pointers, and Crutches **"** Pumps **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"** Boats **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"** Masts, Yards, &c. **"**
 Planksheers **Plating** Keelsons **"** Condition, how ascertained **"**
 Sheerstrakes **"** Clamps and Shelves **"** Sails **"**
 Topsides **"** Ceiling **"** Anchors, No. of **3 Brs 1 1/2 Hedge** **"**
 Wales **"** Rudder **"** Cables **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. Paint When put on **Iron** Hawesers and Warps **"**
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Good**

The vessel placed in the dry dock and bottom scraped painted and coated
 She is now in an efficient state of repair and in our opinion eligible to remain as classed.
 Committee's Minute **4th May** 18 **75** **James P. Bain**
 Character assigned ***A** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. in Reg. Book. **514** No. **1140** Survey held at **London** Date, first Survey **1st April 1875** Last Survey **28th April 1875**
 on the **Iron Ship Roslin Castle** Master **Cuthrie**
 Tonnage **1140** Built at **Glasgow** When built **1863 - 1st Mo.**
 By whom built **Scapier** Owners **Currie & Co.**
 Port belonging to **Liverpool** Destined Voyage **Calcutta**
 If Surveyed Afloat or in Dry Dock **By Dock & Afloat**

Last Survey, No. **10072** Port of **London** Classed ***A** Years assigned **1- 3/4** Character in Register Book **S.S. Gen. 802-1/4**
 Present Condition of the Decks **Good** **Freemasts** **Stretts** **Good**
 Waterways **"** Breasthooks and Stenson **"** Windlass and Capstan **"**
 Comings **"** Transoms, Pointers, and Crutches **"** Pumps **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"** Boats **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"** Masts, Yards, &c. **"**
 Planksheers **Plating** Keelsons **"** Condition, how ascertained **"**
 Sheerstrakes **"** Clamps and Shelves **"** Sails **"**
 Topsides **"** Ceiling **"** Anchors, No. of **3 Brs 1 1/2 Hedge** **"**
 Wales **"** Rudder **"** Cables **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. Paint When put on **Iron** Hawesers and Warps **"**
 Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Good**

The vessel placed in the dry dock and bottom scraped painted and coated
 She is now in an efficient state of repair and in our opinion eligible to remain as classed.
 Committee's Minute **1st May** 18 **75** **James P. Bain**
 Character assigned ***A** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18