

# ANNUAL SURVEYS.

No. in Reg. Book. **1144** on the **Ship S.S. Assyria** Survey held at **London** Date, first Survey **1875** Last Survey **May 1<sup>st</sup> 1875** Recd. 6. 5-75  
 Tonnage **1495** Built at **Renfrew** Master **Heasman** When built **1872** 8<sup>th</sup> Mo.  
 By whom built **Simons** Owners **British India S. S. Co**  
 Port belonging to **Glasgow** Destined Voyage **~**  
 If Surveyed Afloat or in Dry Dock **Dry Dock (Pontoon) and afloat**

Last Survey, No. **13408** Port of **Liverpool** Classed **100** Years assigned. **AI** Character in Register Book. **9-1/4**  
 Present Condition of the Decks **Good** Freenails **~** Rivets **~** Level **~**  
 Waterways **~** Breasthooks and Stemson **~** Windlass and Capstan **~**  
 Comings **~** Transoms, Pointers, and Crutches **~** Pumps **~**  
 Upper Deck Beams & Fastenings **~** ~~Timbers~~ of the Frame at the Openings **~** Boats **~**  
 Lower Deck Beams & Fastenings **~** Ditto ditto at other places **~** Masts, Yards, &c. **~**  
 Planksheers **Plating** Keelsons **~** Condition, how ascertained **~**  
 Sheerstrakes **~** Clamps and Shelves **~** Sails **~**  
 Topsides **~** Ceiling **~** Anchors, No. of **3 Brs 1 In 2 Hedge** **~**  
 Wales **~** Rudder **~** Cables **~**  
~~Plank~~ (Bottom) and Counter **~** Copper or Y.M. Paint When put on **~** Hawers and Warps **~**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Standing and Running Rigging **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **~**

The vessel placed on the pontoon and bottom scraped, painted & coated. She is now in an efficient state of repair and in our opinion eligible to remain as classed. **Senhouse Martindale**

Committee's Minute **11<sup>th</sup> May 1875** **100** **TRW** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **~** Paid **18**

No. in Reg. Book. **86** on the **Ship S.S. Queen Victoria** Survey held at **London** Date, first Survey **~** Last Survey **May 3<sup>rd</sup> 1875**  
 Tonnage **1424** Built at **Sunderland** Master **Reed** When built **1872 - 1<sup>st</sup> Mo**  
 By whom built **Cliff** Owners **Queen Steam Ship Co.**  
 Port belonging to **Liverpool** Destined Voyage **Calcutta**  
 If Surveyed Afloat or in Dry Dock **Dry Dock and afloat**

Last Survey, No. **13331** Port of **Liverpool** Classed **100** Years assigned. **AI** Character in Register Book. **9-1/4**  
 Present Condition of the Decks **Good** Freenails **~** Rivets **~** Level **~**  
 Waterways **~** Breasthooks and Stemson **~** Windlass and Capstan **~**  
 Comings **~** Transoms, Pointers, and Crutches **~** Pumps **~**  
 Upper Deck Beams & Fastenings **~** ~~Timbers~~ of the Frame at the Openings **~** Boats **~**  
 Lower Deck Beams & Fastenings **~** Ditto ditto at other places **~** Masts, Yards, &c. **~**  
 Planksheers **Plating** Keelsons **~** Condition, how ascertained **~**  
 Sheerstrakes **~** Clamps and Shelves **~** Sails **~**  
 Topsides **~** Ceiling **~** Anchors, No. of **3 Brs 1 In 2 Hedge** **~**  
 Wales **~** Rudder **~** Cables **~**  
~~Plank~~ (Bottom) and Counter **~** Copper or Y.M. Paint When put on **~** Hawers and Warps **~**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Standing and Running Rigging **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **~**

The vessel placed in the dry dock and bottom scraped, painted and coated. She is now in an efficient state of repair and in our opinion eligible to remain as classed. **Senhouse Martindale**

Committee's Minute **11<sup>th</sup> May 1875** **100** **TRW** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **~** Paid **18**