

Iron N^o* 14399

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Regd. 13.8.75)
 No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 7th July 1875
429 on the Cocks and Piping of S. S. Elizabeth Martin Tons 1246
 Owners A. Currie Port belonging to Greenock Classified 100 A I
Years assigned. Character in Register Book.

Diameter of Cylinder 30" x 54" Engines made at Glasgow When made 1872
 Length of Stroke 36" Pressure of Steam " By whom made W. Napier & Sons
 Nominal Horse Power 130

Particulars of Repairs and Examination

On examination, the Cocks and Piping in connection with the Machinery and Boilers of this vessel were found to be so arranged, that, by an act of carelessness or neglect water could not be run from the sea into the bilge

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

The Amount of Fee £ : : received by me,
 Certificate (if required) ... £ : : 187

James Bain
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

6. July 18. 875

