

# ANNUAL SURVEYS.

No. in Reg. Book. on the *Iron SS Minerva* Survey held at *London* Date, first Survey *May 11* 1875 Last Survey *May 11* 1875  
 Master *Blackman*  
 Tonnage *1025* Built at *W Hartlepool* When built *1874 - 2M*  
 By whom built *1558* Owners *W H Wise & Co*  
 Port belonging to *W Hartlepool* Destined Voyage   
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *13630* Port of *London* Classed *90A* 11.74  
 Present Condition of the  
 Decks *Good* Treennails *Drifts* *Good*  
 Waterways *do* Breasthooks and Stemson *do*  
 Comings *do* Transoms, Pointers, and Crutches *do*  
 Upper Deck Beams & Fastenings *do* Timbers of the Frame at the Openings *do*  
 Lower Deck Beams & Fastenings *do* Ditto ditto at other places *do*  
 Planksheers *Plating* *do* Keelsons *do*  
 Sheerstrakes *do* *do* Clamps and Shelves *do*  
 Topsides *do* *do* Ceiling *do*  
 Wales *do* *do* Rudder *do*  
 Plank (Bottom) and Counter *do* *do* Copper or Y.M. *Painted* When put on *new*  
 Caulking of Bottom, Deck, & Waterways *Good*  
 Engine Room Skylights *Good* Coal Bunker, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*  
 General Observations, Opinion as to Class, &c. *Bottom Scraped Painted & coated.*

*She is now in an efficient state of repair and in my opinion entitled to remain as Classed*

Committee's Minute *21<sup>st</sup> May* 1875 *Senhouse Martindale*  
 Character assigned *90A* *JBW* Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)  Paid *18*

No. in Reg. Book. on the *Iron SS Walmer Castle* Survey held at *London* Date, first Survey *May 12* 1875 Last Survey *May 12* 1875  
 Master *Webster*  
 Tonnage *1558* Built at *Glasgow* When built *1872 - 4M*  
 By whom built *2485* *2885* Owners *Burclay*  
 Port belonging to *London* Destined Voyage *Cape of Good Hope*  
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *13953* Port of *London* Classed *100A* 11.275  
 Present Condition of the  
 Decks *Good* Treennails *Drifts* *Good*  
 Waterways *do* Breasthooks and Stemson *do*  
 Comings *do* Transoms, Pointers, and Crutches *do*  
 Upper Deck Beams & Fastenings *do* Timbers of the Frame at the Openings *do*  
 Lower Deck Beams & Fastenings *do* Ditto ditto at other places *do*  
 Planksheers *Plating* *do* Keelsons *do*  
 Sheerstrakes *do* *do* Clamps and Shelves *do*  
 Topsides *do* *do* Ceiling *do*  
 Wales *do* *do* Rudder *do*  
 Plank (Bottom) and Counter *do* *do* Copper or Y.M. *Painted* When put on *new*  
 Caulking of Bottom, Deck, & Waterways *Good*  
 Engine Room Skylights *Good* Coal Bunkers, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*  
 General Observations, Opinion as to Class, &c. *Bottom Scraped Painted & coated.*

*She is now in an efficient state of repair and in my opinion entitled to remain as as Classed*

Committee's Minute *21<sup>st</sup> May* 1875 *Senhouse Martindale*  
 Character assigned *100A* *JBW* Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)  Paid *18*