

# ANNUAL SURVEYS.

*114474*  
*Recd 21.5.75*

No. in Reg. Book: 140 **No.** 12546 Survey held at London Date, first Survey 19 May Last Survey 19 May 1875  
 on the Sh. "Pecapolis" Master Almond  
 Tonnage 632 Built at Sunderland When built 1868 8 mo.  
 By whom built Pill Owners J. B. Walker  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 12546 Port of London Classed \_\_\_\_\_  
 Years assigned \_\_\_\_\_ Character in Register Book X/A 1  
S.S. N-1.72  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunker, Openings, Lids, &c. \_\_\_\_\_ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Treenails Ruets  
 Breasthooks and Stenson \_\_\_\_\_  
 Transoms, Pointers, and Crutches \_\_\_\_\_  
 Timbers of the Frame at the Openings \_\_\_\_\_  
 Ditto ditto at other places \_\_\_\_\_  
 Keelsons \_\_\_\_\_  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling \_\_\_\_\_  
 Rudder \_\_\_\_\_  
 Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_

Windlass and Capstan \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Condition, how ascertained \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawsers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_

*The Bottom scraped, cleaned and recoated. This ship appears in good condition and eligible to remain in class.*

Committee's Minute 28<sup>th</sup> May 1875  
 Character assigned X/A 1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

**No.** \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ '18 \_\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Years assigned \_\_\_\_\_ Character in Register Book \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

