

ANNUAL SURVEYS.

No. in Reg. Book. 35 No. 1390 Survey held at London Date, first Survey 22nd April 1875 Last Survey 22nd April 1875
 on the Iron S.S. Gally of Torpe Master Shaw, Martin & Co
 Tonnage 2147 Built at Glasgow When built 1871 - 11th Mo.
 By whom built Wapcar Owners Shaw, Martin & Co
 Port belonging to London Destined Voyage W
 If Surveyed Afloat or in Dry Dock By Dock and afloat.

Last Survey, No. 12425 Port of Iron
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers Plating Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 (Bottom) and Counter " Copper or Y.M. Paint When put on Iron
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. The vessel placed in the dry dock and bottom scraped painted and coated. Machinery and Boilers overhauled and repaired. She is now in an efficient state of repair and in our opinion eligible to remain as classed.

Committee's Minute 27th April 1875 Senhouse Martindale
 Character assigned per Lloyd's Register 100A James Bain
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. 443 No. 1284 Survey held at London Date, first Survey 13th April 1875 Last Survey 13th April 1875
 on the Iron Ship John O'Leary Master Gyall
 Tonnage 1327 Built at Birkenhead When built 1869 - 1st Mo.
 By whom built 1198 Owners Reayley & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock By Dock and afloat.

Last Survey, No. 12682 Port of Iron
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers Plating Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 (Bottom) and Counter " Copper or Y.M. Paint When put on Iron
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. The vessel placed in the dry dock and bottom scraped, painted & coated. She is now in an efficient state of repair and in our opinion eligible to remain as classed.

Committee's Minute 27th April 1875 Senhouse Martindale
 Character assigned per Lloyd's Register 100A James Bain
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18