

No. 168 Survey held at Amsterdam ¹⁴⁵³³ Date February 1874
on the S.S. "Dahlia" Master W. Crawford
Tonnage 2011 Built at Liverpool When built 1872 - 5mo
By whom built Evans Owners Hargrove & Co.
Port belonging to Liverpool Destined Voyage Java
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 14202 Port of Liverpool 7-73 Classed * 100 A. 1.
7.73

The present Condition of the

Decks _____
Waterways _____
Comings _____
Upper Deck Beams & Fastenings _____
Lower Deck Beams & Fastenings _____
Planksheers _____
Sheerstrakes _____
Topsides _____
Wales _____
Plank (Bottom) and Counter _____

Treenails _____
Breasthooks and Stemson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame at the Openings _____
Ditto ditto at other places _____
Keelsons _____
Clamps and Shelves _____
Ceiling _____
Rudder _____
Copper _____ When put on _____

Windlass and Capstan _____
Pumps _____
Boats _____
Masts, Yards, &c. _____
Sails _____
Anchors, No. of _____
Cables _____
Hawsers and Warps _____
Standing and Running Rigging _____


General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

*This vessel has been in the Dry Dock at Nicuue Diep,
but the Master declined a survey.*

Committee's Minute 13th February 1874

Character assigned Deponed *J.P.*



© 2019

Certificate (if required).

Lloyd's Register
Foundation