

ANNUAL SURVEYS.

No. in Reg. Book. **129** No. **1335** Survey held at London Date, first Survey June 3 1875 Last Survey June 3 1875
 on the S Patriarch (Iron) Master Pile
 Tonnage 1405 Built at Aberdeen When built 1869 9 M
 By whom built Hord Owners Thompson & Co
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Dry & Afloat

Last Survey, No. 14332 Port of London
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers Plating Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Painted When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. At present bottom scraped coated & Painted.
She is now in an efficient state of repair and entitled to remain as Classed

Committee's Minute 8th June 1875
 Character assigned AI TBM
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **409** No. **1447** Survey held at London Date, first Survey June 3 1875 Last Survey June 3 1875
 on the S Rodney (Iron) Master "
 Tonnage 1519 Built at Sunderland When built 1876 3 M
 By whom built H Pile Owners Levitt & Mann
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 12600 Port of London
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers Plating Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Painted When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. At present bottom scraped Painted & Coated.

She is now in an efficient state of repair and in my opinion entitled to remain as Classed
 Committee's Minute 8th June 1875
 Character assigned 100A TBM
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18