

ANNUAL SURVEYS.

34645

Recd 8.6.75
May 31/1875

No. in Reg. Book. on the *S Thessalus* Survey held at *London* Date, first Survey _____ Last Survey _____
844 Tonnage *1782* Built at *Glasgow* When built *1874* 7M
 By whom built *Baird* Owners *A. J. H. Carmichael*
 Port belonging to *Greenock* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *13225* Port of *Iron* Classed *100A* 8.74
 Present Condition of the
 Decks *Good* Treennails *Rivets* *Good*
 Waterways *do* Breasthooks and Stenson *"*
 Comings *"* Transoms, Pointers, and Crutches *"*
 Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*
 Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*
 Planksheers *Plating* Keelsons *"*
 Sheerstrakes *"* Clamps and Shelves *"*
 Topsides *"* Ceiling *"*
 Wales *"* Rudder *"*
 Plank (Bottom) and Counter *"* Copper or Y.M. Painted When put on *New*
 Caulking of Bottom, Deck, & Waterways *Good*
 Engine Room Skylights *"* Coal Bunker, Openings, Lids, &c. *"* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped Painted & water
 She is now in an efficient state of repair
 and entitled to remain as Classed*

Committee's Minute *11th June 1875* *Senhouse Martindale*
 Character assigned *100A* *ITW* Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the *S Star of Albion* Survey held at *London* Date, first Survey _____ Last Survey *May 28 18*
893 Tonnage *1782* Built at *Belfast* When built *1864* 7M
 By whom built *Harland* Owners *Couz*
 Port belonging to *Belfast* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *12925* Port of *Iron* Classed *AV* 6.74
 Present Condition of the
 Decks *Good* Treennails *Rivets* *Good*
 Waterways *"* Breasthooks and Stenson *do*
 Comings *"* Transoms, Pointers, and Crutches *"*
 Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*
 Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*
 Planksheers *Plating* Keelsons *"*
 Sheerstrakes *"* Clamps and Shelves *"*
 Topsides *"* Ceiling *"*
 Wales *"* Rudder *"*
 Plank (Bottom) and Counter *"* Copper or Y.M. Painted When put on *New*
 Caulking of Bottom, Deck, & Waterways *Good*
 Engine Room Skylights *"* Coal Bunkers, Openings, Lids, &c. *"* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped Painted & water
 She is now in an efficient state of repair
 and entitled to remain as Classed*

Committee's Minute *11th June 1875* *Senhouse Martindale*
 Character assigned *AV* *ITW* Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____