

ANNUAL SURVEYS.

Paid 14.6.75

No. in Reg. Book. 62 No. 12676 Survey held at London Date, first Survey 11 May Last Survey 12 June 1875
 on the Iron Ship "White Eagle" Master Andrews
 Tonnage 878 Built at Glasgow When built 1855
 By whom built _____ Owners Bilbette
 Port belonging to London Destined Voyage Auckland.
 If Surveyed Afloat or in Dry Dock In Dry Dock and Afloat.

Last Survey, No. 12676 Port of London Classed A.1. Years assigned 4.74 Character in Register Book 6.8.103.73.

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u>	Breasthooks and Stemson <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Timbers of the Frame at the Openings <u>—</u>	Pumps <u>2 main & 5 hand</u>
Deck Beams & Fastenings <u>—</u>	Ditto ditto at other places <u>—</u>	Keelsons <u>—</u>	Boats <u>4, two as life</u>
Deck Beams & Fastenings <u>—</u>	Clamps and Shelves <u>—</u>	Ceiling <u>—</u>	Masts, Yards, &c. <u>—</u>
Planksheers <u>—</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Rudder <u>—</u>	Condition, how ascertained <u>From deck.</u>
Sheerstrakes <u>—</u>	Copper or Y.M. <u>fement</u> When put on _____	Cables <u>Good</u>	Sails <u>2 Suits</u> <u>Good</u>
Wales <u>—</u>	Scuppers <u>Good</u>	Hawsers and Warps <u>and</u>	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Plank (Bottom) and Counter <u>—</u>	Cargo and Main Hatchways <u>Good</u>	Standing and Running Rigging <u>Sufficient</u>	Hatches <u>Good</u>

General Observations, Opinion as to Class, &c. Not done, Renewed the pins of dead-eyes each rigging, riveted an eye plate to boundary angle iron of main channel to take after topgallant back-stays on each side, renewed the fore top-sail yard, main top-gallant mast and cross jack yard, renewed the rudder braces and repainted the bottom. She is now in good condition and eligible in my opinion to remain as classed.

Committee's Minute 18th June 1875 Surveyor J. H. Simmell
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book _____

Present Condition of the Decks _____	Treenails _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Waterways _____	Transoms, Pointers, and Crutches _____	Timbers of the Frame at the Openings _____	Pumps _____
Comings _____	Ditto ditto at other places _____	Keelsons _____	Boats _____
Upper Deck Beams & Fastenings _____	Clamps and Shelves _____	Ceiling _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Caulking of Bottom, Deck, & Waterways _____	Rudder _____	Condition, how ascertained _____
Planksheers _____	Copper or Y.M. _____ When put on _____	Cables _____	Sails _____
Sheerstrakes _____	Scuppers _____	Hawsers and Warps _____	Anchors, No. of _____
Topsides _____	Cargo and Main Hatchways _____	Standing and Running Rigging _____	Hatches _____
Wales _____	Hatches _____		

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

