

14665  
**ANNUAL SURVEYS.**

Rec 14/6/75  
June 8<sup>th</sup> 1875

No. 11141 Survey held at Sunderland Date June 8<sup>th</sup> 1875  
 On the Screw Steamer "Frankland" Master H. Warren  
 Tonnage 141 1/2 Built at Sunderland When built 1869 - 9 Mo  
 By whom built J. Laing Owners H. J. Morton, Lambton Office Sunderland  
 Port belonging to Sunderland Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Simey's Slipway

Last Survey, No. <u>12317</u> / <del>10762</del> Port of <u>Sunderland Iron</u>		Classed <u>90</u> <u>1</u> s.s. Sld. No. <u>1-34</u> <u>1.74</u>	
The present Condition of the			
Decks <u>Good</u>	<del>Fastenings</del> <u>Pivets</u> <u>Good</u>	Windlass and Capstan <u>Iron</u>	} <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>Metal</u>	
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>3 1/2</u>	
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>	
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>where seen</u>	
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 1 S. 2 K</u>	
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>and</u>	
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>	
Wales <u>"</u>	<u>Cement</u> When put on <u>1869</u>	Standing & Running Rigging <u>Sufficient</u>	
Plank (Bottom) and Counter <u>"</u>			
General Observations and Opinion, <u>The bottom coated with 2 coats of black varnish she is now in a good state of repair and eligible in my opinion to remain as classed.</u>		Caulking of Bottom, Deck, and Waterways <u>Good where seen</u>	
Committee's Minute <u>18<sup>th</sup> June 1875</u>		<u>James Gibson</u>	
Character assigned <u>90A1</u>		Certificate (if required)	

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. _____ Port of _____		Classed _____	
The present Condition of the			
Decks _____	Treenails _____	Windlass and Capstan _____	
Waterways _____	Breasthooks and Stemson _____	Pumps _____	
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____	
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____	
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____	
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____	
Sheerstrakes _____	Ceiling _____	Cables _____	
Topsides _____	Rudder _____	Hawsers and Warps _____	
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____	
Plank (Bottom) and Counter _____			
General Observations and Opinion, _____		Caulking of Bottom, Deck, and Waterways _____	
Committee's Minute _____ 18____			
Character assigned _____		Certificate (if required).	