

Report of Survey for Repairs of Engines and Boilers.

No. *24657*
 No. in Reg. Book. *Survey held at* Liverpool Date, first Survey 7th June Last Survey 21st June 1875
 on the Iron S.S. "Strathclyde" Tons 1255
 Owners Barrell & Co Port belonging to Glasgow. Character in Register Book. 100A1.
 Years assigned. 100A1.

Diameter of Cylinder 5 HP 34" LP 60" Engines made at Port Glasgow. When made 1871
 Length of Stroke 42" By whom made Blackwood & Gordon
 Pressure of Steam 60 lbs.
 Nominal Horse Power 180

Particulars of Repairs and Examination

Boilers examined, 8 stay rods renewed, now in good order. Now tested under steam and safety valves set to 60 lbs. pressure.
 Engines examined as far as could be seen overhauled and now in good order. Pipes cocks and connections in good order. Bilge injection pipe has now had chest and non return valve fitted as suggested.

The engines not having been all taken down I am unable to fill in Particulars of Machinery Certificate

The Amount of Fee *ms* £ - : - : received by me, *ms*
 Certificate (if required) ... £ 1 : 1 : " *26/6* 1875
 (Travelling Expenses, if any, £)
 Committee's Minute Lpool 28th June 1875
See Survey Report No 24657
J.E.H.
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.
 Lloyd's Register Foundation
 IRON 462-0066

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write on or below the space for Committee's Minute).