

# ANNUAL SURVEYS.

No. in Reg. Book. **23** No. **1053** Survey held at **London** Date, first Survey **10 June** Last Survey **10 June** 18 **75**  
 on the **Wairato** Master **[Signature]**  
 Tonnage **1053** Built at **Sunderland** When built **1874 - 1 mo.**  
 By whom built **Blumer** Owners **N. Z. S. Co.**  
 Port belonging to **London** Destined Voyage **-**  
 If Surveyed Afloat or in Dry Dock **dry dock**

Last Survey, No. **12496** Port of **London Iron** Classed **100 A1**  
 Years assigned. **3. 74** Character in Register Book.  
 Present Condition of the Decks **Good**  
 Waterways **Good**  
 Comings **Good**  
 Upper Deck Beams & Fastenings **Good**  
 Lower Deck Beams & Fastenings **Good**  
 Planksheers **Good**  
 Sheerstrakes **Good**  
 Topsides **Good**  
 Wales **Good**  
 Plank (Bottom) and Counter **Good**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom scraped and recoated.**

This Ship appears in good condition and eligible to remain as classed.

Committee's Minute **18th June** 18 **75** **Thos. Congdon**  
 Character assigned **100 A1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **PAID** 18 **75**

No. in Reg. Book. **2** No. **13894** Survey held at **London** Date, first Survey **10 June** Last Survey **10 June** 18 **75**  
 on the **Glenale** Master **[Signature]**  
 Tonnage **1389** Built at **W. Hartlepool** When built **1874 - 1 mo.**  
 By whom built **Irvine** Owners **Steel & Young & Co.**  
 Port belonging to **W. Hartlepool** Destined Voyage **-**  
 If Surveyed Afloat or in Dry Dock **dry dock**

Last Survey, No. **13894** Port of **Hartlepool Iron** Classed **90 A1**  
 Years assigned. **2. 75** Character in Register Book.  
 Present Condition of the Decks **Good**  
 Waterways **Good**  
 Comings **Good**  
 Upper Deck Beams & Fastenings **Good**  
 Lower Deck Beams & Fastenings **Good**  
 Planksheers **Good**  
 Sheerstrakes **Good**  
 Topsides **Good**  
 Wales **Good**  
 Plank (Bottom) and Counter **Good**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom recoated.**

This Vessel appears in good condition and eligible to remain as classed.

Committee's Minute **18th June** 18 **75** **Thos. Congdon**  
 Character assigned **90 A1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **PAID** 18 **75**



ANNUAL SURVEYS

Whitkato

Slendale



© 2019

Lloyd's Register  
Foundation