

ANNUAL SURVEYS.

14708
 No. 125 Survey held at London Date June 28th 1875
 on the SS Camilla Master Cole
 Tonnage 728 Built at Newcastle When built 1866 6M
 By whom built Palmer Owners London St Ship Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 12658 Port of Iron Classed 100 A 4.74
SS New No 2-73

The present Condition of the

Decks	<u>Good</u>	Greenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson		"	Pumps
Comings	"	Transoms, Pointers, and Crutches		"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 Bcs. 12 lbs</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables
Topsides	"	Ceiling		"	Hawsers and Warps
Wales	"	Rudder		"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Painted</u>	When put on <u>Now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at present the bottom scraped Painted & Coated
 She is now in an efficient state of Repair and
 entitled to remain as classed.

Senhouse Martindale

Committee's Minute 2nd July 1875

Character assigned

Certificate (if required).

No. 639 Survey held at London Date June 14 1875
 on the Iron S British Nation Master Carnell
 Tonnage 500 Built at Dublin When built 1865 3M
 By whom built Walpole Owners British Ship Owners Co.
 Port belonging to Liverpool Destined Voyage

Vessel's A If Surveyed Afloat or in Dry Dock Dry Dock

TONI

Ditto Survey, No. 13046 Port of Iron Classed *A 7.74
S.S. No. 2.74

Present Condition of the

Decks	<u>Good</u>	Greenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson		"	Pumps
Comings	"	Transoms, Pointers, and Crutches		"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 Bcs. 12 lbs</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables
Topsides	"	Ceiling		"	Hawsers and Warps
Wales	"	Rudder		"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Painted</u>	When put on <u>Good</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

at present the bottom scraped Painted & Coated
 She is now in an efficient state of repair and
 entitled to remain as classed.

Senhouse Martindale

Committee's Minute 2nd July 1875

Character assigned

Certificate (if required).