

ANNUAL SURVEYS.

14723

Recd 9.7.75

No. in Reg. Book. on the 586 **No.** L.S. Survey held at London Date, first Survey 2 July Last Survey 2 July 1875
 Master _____
 Tonnage 1073 Built at Newcastle When built 1862 3 mo. _____
 By whom built Leslie Owners J. Hall Jr. & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 11461 Port of London Iron Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights _____
 Coal Bunker, Openings, Lids, &c. _____
 Scuppers _____
 Cargo and Main Hatchways _____
 Hatches _____
 Treenails _____
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawser and Warps _____
 Standing and Running Rigging _____

General Observations, Opinion as to Class, &c. The Bottom scraped and recoated. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute 13th July 1875 J. R. Congdon
 Character assigned 100A J. R. Congdon Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights _____
 Coal Bunkers, Openings, Lids, &c. _____
 Scuppers _____
 Cargo and Main Hatchways _____
 Hatches _____
 Treenails _____
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawser and Warps _____
 Standing and Running Rigging _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

