

ANNUAL SURVEYS.

14724

Rec 1/7/75
1875

No. 3488 Survey held at W Hartlepool Date 23rd June
 on the Iron S.S. "Maamora" Master Staniland
 Tonnage 648 Built at Hartlepool When built 1868-3 mo
 By whom built J Denton Owners J Herskind & Co
 Port belonging to Hartlepool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Gray's Dry Dock

Last Survey, No. <u>14340</u> Port of <u>Iron</u>		Classed <u>A.1.</u>
The present Condition of the		S.S. No <u>2.75</u> <u>4.55</u>
Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>—</u>	Breasthooks and Stenson <u>—</u>	Pumps <u>—</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>—</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame at the Openings <u>—</u>	Masts, Yards, &c. <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Ditto ditto at other places <u>—</u>	Sails <u>—</u>
Plank sheers <u>—</u>	Keelsons <u>—</u>	Anchors, No. of <u>3 1/2 1st 2nd 3rd</u>
Sheerstrakes <u>—</u>	Clamps and Shelves <u>—</u>	Cables <u>Good</u>
Topsides <u>—</u>	Ceiling <u>—</u>	Hawsers and Warps <u>and</u>
Wales <u>—</u>	Rudder <u>Good and efficient</u>	Standing and Running Rigging <u>sufficient</u>
Plank (Bottom) and Counter <u>—</u>	Copper <u>Cem</u> When put on <u>1868</u>	
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways <u>Good</u>		
Examined bottom after grounding, found a few rivets in bilge keel started; on port side, rivets where started renewed. She is now in good and efficient condition and eligible to remain.		
Committee's Minute <u>2nd July</u> 18 <u>75</u> classed <u>Viz- A.1.</u>		
Character assigned <u>B</u> <u>ITW</u> <u>J W Blayell</u> Certificate (if required).		

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____		Classed _____
The present Condition of the		
Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Plank sheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____		
Committee's Minute _____ 18____		
Character assigned _____		



© 2019

Lloyd's Register
Foundation
Certificate (if required).

IRON 462-0110