

# ANNUAL SURVEYS.

14729

377808

Recd 9.7.75

No.

Survey held at

London

Date

July 8<sup>th</sup> 1875

on the

S Roman Empire

Master

Kennedy

Tonnage

1542  
1542  
1467

Built at

W Hartlepool

When built

1866 1/11

By whom built

Pile

Owners

Duncan & Co

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 12988

Port of

Iron

Classed \*A/ 7.74

58 Lm 112-74

The present Condition of the

Decks	Good	Ironails	Rivets	Good	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of 3 Buoys & 10 fathoms
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	Painted	When put on	New

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present the bottom scraped painted & coated  
She is now in an efficient state of repair  
and entitled to remain as classed

Committee's Minute

13<sup>th</sup> July

18

75

Senhouse Martindale

Character assigned

Certificate (if required).

No.

Survey held at

London

Date

July 8<sup>th</sup> 1875

on the

S British Empire

Master

Mather

Tonnage

1499  
1550  
1436

Built at

Sunderland

When built

1869 9/11

By whom built

W Pile

Owners

G Duncan

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 12568

Port of

Iron

Classed \*A/ 5.74

58 SALM-74

The present Condition of the

Decks	Good	Ironails	Rivets	Good	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of 3 Buoys & 10 fathoms
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	Painted	When put on	New

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present the bottom scraped painted & coated  
She is now in an efficient state of repair  
and entitled to remain as classed

Committee's Minute

13<sup>th</sup> July

18

75

Senhouse Martindale

Character assigned

Certificate (if required).