

Iron No. 14754

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Recd 13.8.75)
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 24 June 1875
208 on the Cocks and piping of S.S. Whampoa 3835 Tons
Owners Hall & Milburn & Co Port belonging to London Classified _____ Years assigned. _____ Character in Register Book. 100 A 1

Diameter of Cylinder 52 x 98 Engines made at Newcastle When made 1874
Length of Stroke 52"
Pressure of Steam "
Nominal Horse Power 500 By whom made Palmer

Particulars of Repairs and Examination

On examination the cocks and piping in connection with the Machinery and Boilers of this vessel were found to be so arranged that by an act of carelessness or neglect water could not be run from the sea into the bilge.

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

The Amount of Fee ... £ 187 received by me, }
Certificate (if required) ... £ _____ 187 }
(Travelling Expenses, if any, £ _____)

James Bain
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ 18

Feb 18. 8. 75