

ANNUAL SURVEYS.

29/7/75
No. in Reg. Book. **No. 26712** Survey held at **Liverpool** Date, first Survey **May 6** Last Survey **June 2** 1875.
on the **Iron Ship "Juliet"** Master **W. Dupuid**
Tonnage **1243** Built at **Belfast** When built **1863-1 M.**
By whom built **Harland** Owners **Bowring & Co.**
Port belonging to **Liverpool** Destined Voyage **Melbourne.**
If Surveyed Afloat or in Dry Dock **Clarence Dry Dock and afloat**

Last Survey, No. **12648** Port of **Iron** Classed ***A** Years assigned **14** Character in Register Book ***A**
Present Condition of the Decks **Good**
Waterways **"**
Comings **"**
Upper Deck Beams & Fastenings **Iron**
Lower Deck Beams & Fastenings **and good**
Planksheers **"**
Sheerstrakes **"**
Topsides **"**
Wales **"**
Plank (Bottom) and Counter **painted**
Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**
General Observations, Opinion as to Class, &c. **Now done. Bottom scraped and painted. She is in good condition and in my opinion eligible to remain as Classed *A.**

Committee's Minute **Liverpool 3rd August 1875**
Character assigned ***A**

D. F. Light
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **Paid** 18

No. in Reg. Book. **No. 122** Survey held at **Liverpool** Date, first Survey **June 9** Last Survey **June 24** 1875.
on the **Iron Ship "Cholula"** Master **P. Cox**
Tonnage **1066** Built at **Birkenhead** When built **1867-3 M.**
By whom built **1869** **Clover** Owners **Willis & Co.**
Port belonging to **Liverpool** Destined Voyage **Calcutta**
If Surveyed Afloat or in Dry Dock **Clarence Dry Dock**

Last Survey, No. **12922** Port of **Iron** Classed ***A** Years assigned **12** Character in Register Book ***A**
Present Condition of the Decks **Good**
Waterways **"**
Comings **"**
Upper Deck Beams & Fastenings **Iron and**
Lower Deck Beams & Fastenings **good**
Planksheers **"**
Sheerstrakes **"**
Topsides **"**
Wales **"**
Plank (Bottom) and Counter **painted**
Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**
General Observations, Opinion as to Class, &c. **Now done. Bottom scraped and painted. Rudder pintles and braces repaired and refitted and re-riveted. Some iron pillars taken down set fair and refitted. She is now in good condition and in my opinion eligible to remain as Classed *A.**

Committee's Minute **Liverpool 3rd August 1876**
Character assigned ***A**

D. F. Light
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **Paid** 18

"Juliet"

"Cholula" 24412



© 2019

Lloyd's Register
Foundation