

# ANNUAL SURVEYS.

Rec<sup>d</sup> 23.7.75

No. in Reg. Book. **175** Survey held at **London** Date, first Survey **7<sup>th</sup> July** Last Survey **16<sup>th</sup> July** 1875  
 on the **Iron Screw Sm<sup>r</sup> Fingal** Master **George Briggs**  
 Tonnage **559.823** Built at **Lesh** When built **1862** 12<sup>th</sup> mth  
 By whom built **Morton** Owners **J. Casey**  
 Port belonging to **London** Destined Voyage **Jaganrog**  
 If Surveyed Afloat or in Dry Dock **Commercial dry dock & mill wall afloat**

Last Survey, No. **12791** Port of **Iron**

Classed **90A.1** Character in Register Book. **S.S. No 3/23**  
 5.74

Present Condition of the Decks	<b>good</b>	Treenails	<b>Rivets where seen</b>	<b>good</b>
Waterways	"	Breasthooks and Stemson		"
Comings	"	Transoms, Pointers, and Crutches		"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"
Planksheers	"	Keelsons		"
Sheerstrakes	"	Clamps and Shelves		"
Topsides	"	Ceiling		"
Wales	"	Rudder <b>efficient</b>		"
Plank (Bottom) and Counter	"	Copper or Y.M.	When put on	
		Caulking of Bottom, Deck, & Waterways	<b>good</b>	

Windlass and Capstan **in good order**  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Condition, how ascertained **from the deck** "  
 Sails "  
 Anchors, No. of **3 B. 1 S. 2 K** "  
 Cables "  
 Hawesers and Warps "  
 Standing and Running Rigging "

Engine Room Skylights **good** Coal Bunker, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **Clean'd the bottom, and recoated it. Clean'd her out inside. - Untung the Rudder and repaired it. Rebrush'd the pintles and braces, renew'd all rivets in the Rudder found doubtful or bad. Repitted it, made good the stuffing box, and put all in order.**  
**She is now in good condition, and in my opinion is entitled to remain as class'd 90.A.1.**

Committee's Minute **27<sup>th</sup> July** 1875  
 Character assigned **90 A.1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18

No. in Reg. Book. **732** Survey held at **London** Date, first Survey **15<sup>th</sup> July** Last Survey **July 21<sup>st</sup>** 1875  
 on the **Iron Screw Brig Burmese** Master **J. G. Luck**  
 Tonnage **1269.1951.1316** Built at **S. Shields** When built **1873** 12<sup>th</sup> mth  
 By whom built **Selfly** Owners **J. Sutton**  
 Port belonging to **N. Shields** Destined Voyage **Cardiff**  
 If Surveyed Afloat or in Dry Dock **Brisannin dry dock**

Last Survey, No. **14571** Port of **Iron**

Classed **100A.1** Character in Register Book. **1.75**

Present Condition of the Decks	<b>good</b>	Treenails	<b>Rivets where seen</b>	<b>good</b>
Waterways	"	Breasthooks and Stemson		"
Comings	"	Transoms, Pointers, and Crutches		"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"
Planksheers	"	Keelsons		"
Sheerstrakes	"	Clamps and Shelves		"
Topsides	"	Ceiling		"
Wales	"	Rudder <b>efficient</b>		"
Plank (Bottom) and Counter	"	Copper or Y.M.	When put on	
		Caulking of Bottom, Deck, & Waterways	<b>good</b>	

Windlass and Capstan **in good order**  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Condition, how ascertained **from the deck** "  
 Sails "  
 Anchors, No. of **3** "  
 Cables "  
 Hawesers and Warps "  
 Standing and Running Rigging "

Engine Room Skylights **good** Coal Bunkers, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **Clean'd the bottom, overhauled her as far as practicable inside and outside. Took the Cap off the counter or neck of Rudder and put it in order. She is in good condition and in my opinion, is entitled to remain as class'd 100.A.1.**

Committee's Minute **27<sup>th</sup> July** 1875  
 Character assigned **100 A.1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18