

ANNUAL SURVEYS.

No. in Reg. Book. *28* No. *14903* Survey held at *London* Date, first Survey *15 Aug* Last Survey *15 August 1875*
 on the *S. Watarawa* Master *Hodder*
 Tonnage *883* Built at *P. Glasgow* When built *1863*
 By whom built *778* Owners *N. L. S. Co.*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *dry dock*

Last Survey, No. *13073* Port of *London* Classed *Years assigned. Character in Register Book. *A1-714 S.S. Lish-2.72*
 Present Condition of the Decks *Good*
 Waterways *Good*
 Comings *Good*
 Upper Deck Beams & Fastenings *Good*
 Lower Deck Beams & Fastenings *Good*
 Planksheers *Good*
 Sheerstrakes *Good*
 Topsides *Good*
 Wales *Good*
 Plank (Bottom) and Counter *Good*
 Engine Room Skylights *Good*
 Coal Bunker, Openings, Lids, &c. *Good*
 Scuppers *Good*
 Cargo and Main Hatchways *Good*
 Hatches *Good*
 Treennails *Good*
 Breasthooks and Stems *Good*
 Transoms, Pointers, and Crutches *Good*
 Timbers of the Frame at the Openings *Good*
 Ditto ditto at other places *Good*
 Keelsons *Good*
 Clamps and Shelves *Good*
 Ceiling *Good*
 Rudder *Good*
 Copper or I.M. *Good* When put on
 Caulking of Bottom, Deck, & Waterways *Good*
 Windlass and Capstan *Complete*
 Pumps *Complete*
 Boats *Complete*
 Masts, Yards, &c. *Complete*
 Condition, how ascertained *and*
 Sails *and*
 Anchors, No. of *and*
 Cables *efficient*
 Hawsers and Warps *efficient*
 Standing and Running Rigging *efficient*

Bottom cleaned and recoated. This ship appears in good condition and eligible to remain as classed.

Committee's Minute *20th August 1875* Character assigned **A1*
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) *Yes* Paid *18*

No. in Reg. Book. *315* No. *14904* Survey held at *London* Date, first Survey *14 Aug* Last Survey *14 August 1875*
 on the *S. North* Master *Hillman*
 Tonnage *1344* Built at *P. in Kent* When built *1868*
 By whom built *1198* Owners *J. & C.*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *dry dock*

Last Survey, No. *13246* Port of *London* Classed *Years assigned. Character in Register Book. *A1-9.0 S.S. Lish-1.72*
 Present Condition of the Decks *Good*
 Waterways *Good*
 Comings *Good*
 Upper Deck Beams & Fastenings *Good*
 Lower Deck Beams & Fastenings *Good*
 Planksheers *Good*
 Sheerstrakes *Good*
 Topsides *Good*
 Wales *Good*
 Plank (Bottom) and Counter *Good*
 Engine Room Skylights *Good*
 Coal Bunkers, Openings, Lids, &c. *Good*
 Scuppers *Good*
 Cargo and Main Hatchways *Good*
 Hatches *Good*
 Treennails *Good*
 Breasthooks and Stems *Good*
 Transoms, Pointers, and Crutches *Good*
 Timbers of the Frame at the Openings *Good*
 Ditto ditto at other places *Good*
 Keelsons *Good*
 Clamps and Shelves *Good*
 Ceiling *Good*
 Rudder *Good*
 Copper or I.M. *Good* When put on
 Caulking of Bottom, Deck, & Waterways *Good*
 Windlass and Capstan *Complete*
 Pumps *Complete*
 Boats *Complete*
 Masts, Yards, &c. *Complete*
 Condition, how ascertained *and*
 Sails *and*
 Anchors, No. of *and*
 Cables *efficient*
 Hawsers and Warps *efficient*
 Standing and Running Rigging *efficient*

Bottom cleaned and recoated. Rudder bushes bushed. This ship appears in good condition and eligible to remain as classed.

Committee's Minute *20th August 1875* Character assigned **A1*
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) *Yes* Paid *18*

Waitara



© 2019

Lloyd's Register
Foundation