

ANNUAL SURVEYS.

No. in **W6.** Survey held at London Date, first Survey Read 29.7.75
 Reg. Book. on the S Samuel Plimsoll Master July 27 1875
 167 Tonnage 1444 Built at Aberdeen When built 1873 SM
 By whom built Hood Owners J. Thompson Junr
 Port belonging to Aberdeen Destined Voyage
 If Surveyed Afloat or in Dry Dock By SH

Last Survey, No. 13068 Port of London Classed 100A 8.74
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Painted When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped Painted & brased
 She is now in an efficient state of
 repair and entitled to remain as classed*

Committee's Minute 6th August 1875 Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. **W6.** Survey held at London Date, first Survey July 3 1875
 Reg. Book. on the S Star of Germany Master
 949 Tonnage 1284 Built at Belfast When built 1872 SM
 By whom built Harlan Owners Barry & Co
 Port belonging to Belfast Destined Voyage
 If Surveyed Afloat or in Dry Dock By SH

Last Survey, No. 13870 Port of London Classed 100A 8.74
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Painted When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped Painted & brased
 She is now in an efficient state of repair
 and entitled to remain as classed*

Committee's Minute 6th August 1875 Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18