

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 2478** Survey held at **Birkenhead** Date, first Survey **August 23<sup>rd</sup>** Last Survey **August 31<sup>st</sup>** 18 **75**.  
 on the **Wm W. S. "Good Hope"** Master **Baindon**

**TONNAGE** under Tonnage Deck  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop, or Raised Or. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage **1555**  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm. **1018**  
 Built at **Sunderland** When built **1868-6**  
 Owners **J. Laim** Port belonging to **London**  
 Residence **Sunderland**  
 By whom built **Laim** Destined Voyage **not known**  
 If Surveyed Afloat or in Dry Dock **Messrs Clover's Dry Dock**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.**  
 Last Survey, No. **13852** Port **Iron** Character in Register Book **90 A 1**  
 Classified **S.S. 401-71 1-75**

REPAIRS, OR EXAMINATION AS PER RULE

**Damage**

**Work done.** Two parboards platis on the port side ap-  
 renewed, Cement made good in way of the same and  
 the bottom scraped and painted.

Cause of Repairs to be clearly stated.

Present Condition of the				
Decks	<b>good</b>	Trunnels	<b>Rivets good</b>	Windlass and Capstan
Waterways	<b>"</b>	Breasthooks and Stenson	<b>"</b>	Pumps
Comings	<b>"</b>	Transoms, Porters, and Crutches	<b>"</b>	Boats
Upper Deck Beams & Fastenings	<b>Iron</b>	Timbers of the Frame at the openings	<b>"</b>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<b>good</b>	Ditto Ditto at other places	<b>"</b>	Condition, how ascertained
Planksheers	<b>"</b>	Keelsons	<b>"</b>	Sails
Sheerstrakes	<b>"</b>	Clamps and Shelves	<b>"</b>	Anchors
Topsides	<b>"</b>	Ceiling	<b>"</b>	No. of
Wales	<b>"</b>	Rudder	<b>"</b>	Cables
Plank (Bottom) and Counter	<b>painted</b>	Copper	<b>Cement When put on 1868</b>	Hawsers and Warps
Engine Room Skylights	<b>good</b>	Caulking of	<b>good</b>	Standing & Running Rigging
Coal Bunker, Openings, Lids, &c.	<b>good</b>	Bottom, Deck, & Waterways	<b>good</b>	Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.		Scuppers	<b>good</b>	Hatches

**This vessel is now in good condition and in my opinion eligible to remain as Classed 90 A 1.**

The Amount of Entry Fee ... £ ... : : : received by me, **J. F. Lister**  
 Special day ... £ **3 : 3 : 0** 3/9/1875  
 Certificate (if required) ... £ ... : : :  
 (Travelling Expenses, if any, £ ...)

Committee's Minute **Liverpool 14<sup>th</sup> September 1875**

Character assigned **90 A 1**

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019 Lloyd's Register Foundation

IRON462-0459



"Good Hope"  
24458



© 2019

Lloyd's Register  
Foundation