

# ANNUAL SURVEYS.

No. in Reg. Book. **387** No. **13307** Survey held at **London** Date, first Survey **Aug 26** Last Survey **1875**  
 on the **SS Glenora** Master **Le Trianon**  
 Tonnage **764** Built at **Liverpool** When built **1864** 7M  
 By whom built **Vernon** Owners **Shaw Savill & Co**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13307** Port of **London** Classed **A1** Years assigned **9.74** Character in Register Book **SS Len M 2-73**  
 Present Condition of the Decks **Good** Treennails **Good**  
 Waterways **Good** Breasthooks and Stemson **Good**  
 Comings **Good** Transoms, Pointers, and Crutches **Good**  
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**  
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**  
 Planksheers **Good** Keelsons **Good**  
 Sheerstrakes **Good** Clamps and Shelves **Good**  
 Topsides **Good** Ceiling **Good**  
 Wales **Good** Rudder **Good**  
 Plank (Bottom) and Counter **Good** Copper or Y.M. Painted When put on **Good**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **Good**  
 Boats **Good**  
 Masts, Yards, &c. **Good**  
 Condition, how ascertained **Good**  
 Sails **Good**  
 Anchors, No. of **3 B & 2 P** **Good**  
 Cables **Good**  
 Hawesers and Warps **Good**  
 Standing and Running Rigging **Good**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **at present Bottom Scraped Painted**  
*She is now in an efficient state of repair and entitled to remain as classed*

Committee's Minute **3<sup>rd</sup> September 1875** Character assigned **A1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

No. in Reg. Book. **398** No. **13213** Survey held at **London** Date, first Survey **Aug 6** Last Survey **1875**  
 on the **S Pleiades** Master **Williams**  
 Tonnage **997** Built at **Gumbarton** When built **1869** 7M  
 By whom built **Mc Millan** Owners **Shaw Savill & Co**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13213** Port of **London** Classed **A1** Years assigned **8.74** Character in Register Book **SS Len M 2-73**  
 Present Condition of the Decks **Good** Treennails **Good**  
 Waterways **Good** Breasthooks and Stemson **Good**  
 Comings **Good** Transoms, Pointers, and Crutches **Good**  
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**  
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**  
 Planksheers **Good** Keelsons **Good**  
 Sheerstrakes **Good** Clamps and Shelves **Good**  
 Topsides **Good** Ceiling **Good**  
 Wales **Good** Rudder **Good**  
 Plank (Bottom) and Counter **Good** Copper or Y.M. Painted When put on **Good**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **Good**  
 Boats **Good**  
 Masts, Yards, &c. **Good**  
 Condition, how ascertained **Good**  
 Sails **Good**  
 Anchors, No. of **3 B & 2 P** **Good**  
 Cables **Good**  
 Hawesers and Warps **Good**  
 Standing and Running Rigging **Good**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **at present Bottom Scraped Painted**  
*She is now in an efficient state of repair and entitled to remain as classed*

Committee's Minute **3<sup>rd</sup> September 1875** Character assigned **A1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**