

15088

ANNUAL SURVEYS.

31.9.34
Rec'd 26.8.75

No. 1 Survey held at London Date, first Survey 20 Aug Last Survey 20 August 1875
 in Book on the "Line" Master _____
 Tonnage 847 Built at Lundeland When built 1874 5 mo.
 By whom built Pile Owners Sellis
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 12982 Port of St. John Classed _____ Years assigned _____ Character in Register Book 100 A1
6.74

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Treenails <u>11 rivets</u> Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawser and Warps _____ Standing and Running Rigging _____
--	--	---

General Observations, Opinion as to Class, &c. Bottom scraped, cleared and recoated. This ship appears eligible to remain as classed.

Committee's Minute 31st August 1875 W. Couper
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 in Reg. Book on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book _____

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Treenails _____ Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawser and Warps _____ Standing and Running Rigging _____
---	---	---

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



IRON 463-0094

ANNUAL SURVEY

1787



© 2019

Lloyd's Register Foundation